




INTELLICHLOR®



INTELLICHLOR®

Replacement Parts

No.	Part No.	Description	Part No.	Includes
1	H-52-0595	Replacement Union Set		2
2	520736	Flow Switch replacement kit		1
Not Shown				
	H-52-0881	Replacement Cell IC20		
	H-52-0882	Replacement Cell IC40		
	H-52-0883	IC20 & IC40 Transfo		
	H-52-0884	Spacer Cell (for start-up or winterization) Acid Washing Kit		
	520670	(incl. Closed end union cap, o-ring and coupling nut)		
	521147	Gasket Kit - Set of 10 o-rings		
	H-52-0594	Diagnostic Wand		

Rev. 08/2016

AUTOMATION

FILTERS

FILTER
SYSTEMS

PUMPS

HEAT PUMPS

CLEANERS

WATER
FEATURES

LIGHTS

SALT
CHLORINATORSDOSING &
MEASURING

SANITIZERS

WHITE
GOODSMAINTENANCE
ACCESSORIES

OTHER